



Confederated Tribes of Warm Springs, Oregon
Public Utilities Branch
PO Box 1196
Warm Springs, OR 97761
Phone: (541) 553-3246
Fax: (541) 553-3380

PUBLIC NOTICE:
Pertaining to the
Confederated Tribes of Warm Springs Reservation of
Oregon
POTABLE WATER SUPPLIES

Pursuant to Water System ID# 104101247 Administrative Compliance Order on Consent issued by EPA May 2019, authorized by Section 1414(g) of the Safe Water Drinking Act ("SDWA"), 42 USC 300g-3(g) find the following list of items associated with the water supply to be out of compliance with the regulation. The Warm Springs Public Works department is actively working to resolve the issue through several existing and ongoing projects

Table 1 is a summary of the requirements of the Consent Order and the status of those requirements.

This notice is signed under the authority vested in the Operations General Manager by the Tribal Council.

Chico Holliday

General Manager
Public Utilities

Water/Wastewater Manager

+1 (541) 460-2707 (c)

+1 (541) 615-0962 (w)

Chico.holliday@wstribes.org



Confederated Tribes of Warm Springs, Oregon
 Public Utilities Branch
 PO Box 1196
 Warm Springs, OR 97761
 Phone: (541) 553-3246
 Fax: (541) 553-3380

Table 1: CONSENT ORDER SUMMARY:

| NO.: | ORDER REF: | DESCRIPTION | STATUS |
|------|------------|---|---|
| 1 | 4.1a | Conform to Coagulation Chemical SOP | Ongoing |
| 2 | 4.1b | Tee-Wee-Bute Tank Hatch Gaskets | Work Complete |
| 3 | 4.1c | Tee-Wee-Bute Tank New Roof Vent & Screen | Work Complete |
| 4 | 4.1d | Kah-Nee-Ta Tank Hatch Gasket & Lock | Work Complete |
| 5 | 4.1e | Southeast Tank Screen Overflow | Work Complete |
| 6 | 4.1f | Southeast Tank New Roof Vent & Screen | Work Complete |
| 7 | 4.1g | West Hills- West Tank Hatch Gasket & Lock | Work Complete |
| 8 | 4.1h | West Hills West Tank Screen Overflow | Work Complete |
| 9 | 4.1i | West Hills East Tank New Ladder & Safety cage | Work Complete |
| 10 | 4.1k | West Hills West Tank New Ladder & Safety cage | Work Complete |
| 11 | 4.1l | Greely Heights West Tank hatch gasket | Work Complete |
| 12 | 4.1m | Greely Heights East Tank Screen Overflow | Work Complete |
| 13 | 4.1n | Greely Heights East Tank New Ladder & Safety cage | Work Complete |
| 14 | 4.1o | Service & Repair HVAC WTP - Service and repair and/or upgrade HVAC system in water treatment plant to provide adequate ventilation for heat and moisture dissipation. | Part of PDB Project – multiple issues to be addressed with ducting, air handlers, and controllers |
| 15 | 4.1p | Clean Sedimentation Tanks | Ongoing |
| 16 | 4.1q | Repair Sampling System IFE#2 | Work Complete |
| 17 | 4.1r | Raw Water Intake Screen Repair | Part of PDB Project |
| 18 | 4.1s | Reduce Turbidity meter sampling delay | Work Complete |
| 19 | 4.1t | Isolate Concrete Water Storage Tank | Work Complete |
| 20 | 4.2 | Sanitary Notice | Ongoing |
| 21 | 4.3 | Public Notice | Ongoing |
| 22 | 4.4 | EPA Notice | Ongoing |



Confederated Tribes of Warm Springs, Oregon
Public Utilities Branch
PO Box 1196
Warm Springs, OR 97761
Phone: (541) 553-3246
Fax: (541) 553-3380

PUBLIC NOTICE:
Pertaining to the
Confederated Tribes of Warm Springs Reservation of
Oregon
POTABLE WATER SUPPLIES

Pursuant to Water System ID# 104101247 Administrative Emergency Order on Consent issued by EPA June 2019, authorized by Section 1414(g) of the Safe water Drinking Act ("SDWA"), 42 USC 300g-3(g) find the following list of items associated with the water supply to be out of compliance with the regulation.

The Warm Springs Public Works department is actively working to resolve the issue through several existing and ongoing projects

Table 1 is a summary of the requirements of the **Emergency Order** and the status of those requirements.

This notice is signed under the authority vested in the Operations General Manager by the Tribal Council.

Chico Holliday 
General Manager
Public Utilities
Water/Wastewater Manager

+1 (541) 460-2707 (c)

+1 (541) 615-0962 (w)

Chico.holliday@wstribes.org



Confederated Tribes of Warm Springs, Oregon
 Public Utilities Branch
 PO Box 1196
 Warm Springs, OR 97761
 Phone: (541) 553-3246
 Fax: (541) 553-3380

| NO.: | ORDER REF: | DESCRIPTION | STATUS |
|------|------------|--|--|
| 1 | 3:20 | Coordinate Order Response | Complete/Part of PDB Project |
| 2 | 3:21 | Respond | Complete/Part of PDB Project |
| 3 | 3:22 | Engineering Report for WTP & Distribution timeline | Part of PDB Project |
| 4 | 3:23 | Engineering Report Presentation | |
| 5 | 3:24 | Engineering Report to include but not be limited to: - Turbidity, Low Pressure, Chlorine Residual, Reliability & Operability | |
| 6 | 3:25 | Engineering Report Final | |
| 7 | 3:26f | Conform to Coagulation Chemical SOP | Ongoing |
| 8 | 3:28 | Prepare Coagulation Chemical SOP | Ongoing |
| 9 | 3:26g | Perform Daily Jar Testing | Ongoing |
| 10 | 3:26j | Colorimeters – use appropriate reagent | Ongoing |
| 11 | 3:26k | Update Cross Connection Plan | Work Complete |
| 12 | 3:27 | Clean Sedimentation Tanks | Ongoing/Part of PDB Project |
| 13 | 3:24 | PAC relocation/enclosure | Part of PDB Project |
| 14 | 3:26l | Filter Media Replacement | |
| 15 | 3:26i | Filter Media Review - Perform a self-assessment of the backwash process to ensure adequate cleaning of the filter media...use this assessment to create a Standard Operating Procedure for the Plant's backwash process. | |
| 16 | 3:26h | Sample Pump Renewal - Make repairs to the suction lift line in sampling pump at IFE #2 to ensure turbidity measurement is accurate. | Work completed by IHS – To be reevaluated by PDB Project |
| 17 | | Settling Pond Lining | Part of PDB Project |
| 18 | 3:26e | Finished Water Lift Pumps | Ongoing |
| 19 | 3:26c | Finish Water Flow Control Valves | Work Complete |
| 20 | | HVAC Repair | Part of PDB Project |
| 21 | 3:29 | Raw Water Intake Screen Repair-Upgrade River intake air scour system to provide for appropriate operation. | Part of PDB Project |
| 22 | | Raw Water Pumps System | |
| 23 | 3:26d | SCADA update - Repair the SCADA system, known as the distributed Control Systems, to ensure proper operation. | |
| 24 | 3:26a | Turbidity Meters Automate - Install automated turbidimeters with alarms and shutoff features to prevent turbidity exceedances | |
| 25 | 3:26b | Raw Water Flow Meter - Install flow meters for incoming raw water to ensure proper adjustment of coagulation dosage and water volume at every step of the treatment process. | |
| 26 | | Septic System Replacement | |
| | | | Partial/Part of PDB Project. |

Table 1: EMERGENCY ORDER (Sec. 1431) STATUS