



Confederated Tribes of Warm Springs, Oregon
Public Utilities Branch
PO Box 1196
Warm Springs, OR 97761
Phone: (541) 553-3246
Fax: (541) 553-3380

PUBLIC NOTICE:

Pertaining to the

Confederated Tribes of Warm Springs Reservation of

Oregon

POTABLE WATER SUPPLIES

Pursuant to Water System ID# 104101247 Administrative Compliance Order on Consent issued by EPA May 2019, authorized by Section 1414(g) of the Safe water Drinking Act ("SDWA"), 42 USC 300g-3(g) find the following list of items associated with the water supply to be out of compliance with the regulation. The Warm Springs Public Works department is actively working to resolve the issue through several existing and ongoing projects

Table 1 is a summary of the requirements of the Consent Order and the status of those requirements.

This notice is signed under the authority vested in the Operations General Manager by the Tribal Council.

Chico Holliday

General Manager

Public Utilities

Water/Wastewater Manager

+1 (541) 460-2707 (c)

+1 (541) 615-0962 (w)

Chico.holliday@wstribes.org



Confederated Tribes of Warm Springs, Oregon
 Public Utilities Branch
 PO Box 1196
 Warm Springs, OR 97761
 Phone: (541) 553-3246
 Fax: (541) 553-3380

Table 1: CONSENT ORDER SUMMARY:

NO.:	ORDER REF:	DESCRIPTION	STATUS
1	4.1a	Conform to Coagulation Chemical SOP	Ongoing
2	4.1b	Tee-Wee-Bute Tank Hatch Gaskets	Work Complete
3	4.1c	Tee-Wee-Bute Tank New Roof Vent & Screen	Work Complete
4	4.1d	Kah-Nee-Ta Tank Hatch Gasket & Lock	Work Complete
5	4.1e	Southeast Tank Screen Overflow	Work Complete
6	4.1f	Southeast Tank New Roof Vent & Screen	Work Complete
7	4.1g	West Hills- West Tank Hatch Gasket & Lock	Work Complete
8	4.1h	West Hills West Tank Screen Overflow	Work Complete
9	4.1i	West Hills East Tank New Ladder & Safety cage	Work Complete
10	4.1k	West Hills West Tank New Ladder & Safety cage	Work Complete
11	4.1l	Greely Heights West Tank hatch gasket	Work Complete
12	4.1m	Greely Heights East Tank Screen Overflow	Work Complete
13	4.1n	Greely Heights East Tank New Ladder & Safety cage	Work Complete
14	4.1o	Service & Repair HVAC WTP - Service and repair and/or upgrade HVAC system in water treatment plant to provide adequate ventilation for heat and moisture dissipation.	Part of PDB Project – multiple issues to be addressed with ducting, air handlers, and controllers
15	4.1p	Clean Sedimentation Tanks	Ongoing
16	4.1q	Repair Sampling System IFE#2	Work Complete
17	4.1r	Raw Water Intake Screen Repair	Part of PDB Project
18	4.1s	Reduce Turbidity meter sampling delay	Work Complete
19	4.1t	Isolate Concrete Water Storage Tank	Work Complete
20	4.2	Sanitary Notice	Ongoing
21	4.3	Public Notice	Ongoing
22	4.4	EPA Notice	Ongoing